



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

67035

Customer Information:

Company	WEBB RESEARCH CORPORATION	Date	1/13/2012
Contact	Beth Rizzo		
PO Number	TWR5751		

Serial Number	WEBB Glider-0047
Model Number	WEBB Glider

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

1. The anti-foulant devices appeared "dirty".

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
3. Calibrated the pressure sensor.
4. Installed NEW AF24173 Anti-foulant cylinder(s).
5. Performed complete system check and full diagnostic evaluation.

Special Notes:

--